

How to charge your Li-ion Zero Wire-free Motor



STEP 1

Rotate cover cap to expose motor head

STEP 2

Find nearest power source and plug in charger
(use an extension cord if required)



STEP 3

Plug micro USB end into the motor

- Observe the green light flashing and charge until the green light goes solid green
 - Please note this may take up to eight hours depending on how flat your battery is
 - Any mobile phone charger can also be used to charge your motor.
-

STEP 4

Unplug and return cover cap to conceal motor head

